Mainline 6B 2012 Maintenance and Rehabilitation & Line 6B Replacement Projects IDEM Water Quality Certification Independent Environmental Monitor Weekly Observation Report



sta#1550+00_MP494.4_W-494-C_ECD'S in working order_SW working order_SW



sta#1563+89_MP494.6_S-494-B_Waterbody ECD'S in



sta#1662+00_MP496.6_S-496-C_ECD'S in working order_E



sta#1724+00_MP497.7_W-497-C_ECD'S in need of repair _NE



sta#1912+00_MP501.2_W-501-B_ECD'S in working order_N



